

Edgar Filing: UNISOURCE ENERGY CORP - Form 8-K

UNISOURCE ENERGY CORP
Form 8-K
August 22, 2005

UNITED STATES
SECURITIES AND EXCHANGE COMMISSION
Washington, D.C. 20549

FORM 8-K

CURRENT REPORT
PURSUANT TO SECTION 13 OR 15(d) OF THE
SECURITIES EXCHANGE ACT OF 1934

DATE OF REPORT
(DATE OF EARLIEST EVENT REPORTED): August 11, 2005

Commission File Number	Registrant; State of Incorporation; Address; and Telephone Number	IRS Employer Identification Number
1-13739	UNISOURCE ENERGY CORPORATION (An Arizona Corporation) One South Church Avenue, Suite 100 Tucson, AZ 85701 (520) 571-4000	86-0786732
1-5924	TUCSON ELECTRIC POWER COMPANY (An Arizona Corporation) One South Church Avenue, Suite 100 Tucson, AZ 85701 (520) 571-4000	86-0062700

Check the appropriate box below if the Form 8-K filing is intended to simultaneously satisfy the filing obligation of the registrant under any of the following provisions:

Written communications pursuant to Rule 425 under the Securities Act (17 CFR 230.425)

Soliciting material pursuant to Rule 14a-12 under the Exchange Act (17 CFR 240.14a-12)

Pre-commencement communications pursuant to Rule 14d-2(b) under the Exchange Act (17 CFR 240.14d-2(b))

Pre-commencement communications pursuant to Rule 13e-4(c) under the Exchange Act (17 CFR 240.13e-4(c))

Item 8.01 - Other Events.

On August 11, 2005, Tucson Electric Power Company's (TEP) 380 megawatt Springerville Generating Station Unit 2 (Springerville Unit 2) was taken out of service due to a control system malfunction and subsequent mechanical problem with the turbine. TEP has determined that one row of turbine blades was damaged and will need to be replaced. Replacement blades are now being machined by the

Edgar Filing: UNISOURCE ENERGY CORP - Form 8-K

manufacturer. The exact length of the outage has not been determined but based on current information, TEP expects Springerville Unit 2 to be returned to service sometime during the week of September 4, 2005.

TEP has contracted to purchase replacement power in the market to meet its retail load requirements during the Springerville Unit 2 outage, which is estimated to increase costs by approximately \$500,000 per day. TEP's retail rates are currently capped therefore none of these replacement power costs can be passed through to retail customers. The repair costs are expected to be less than \$1 million.

Item 7.01 - Regulation FD Disclosure.

Although the total financial impact of the Springerville Unit 2 outage cannot be determined at this time, UniSource Energy Corporation (UniSource Energy) expects the costs of the outage to result in reduced 2005 full-year earnings. UniSource Energy is currently unable to determine whether 2005 full-year earnings will be within the previous estimated range of \$1.50 and \$1.75 per basic share.

SIGNATURES

Pursuant to the requirements of the Securities Exchange Act of 1934, each registrant has duly caused this report to be signed on its behalf by the undersigned thereunto duly authorized.

Date: August 22, 2005

UNISOURCE ENERGY CORPORATION

(Registrant)

/s/ Kevin P. Larson

Vice President and Principal
Financial Officer

Date: August 22, 2005

TUCSON ELECTRIC POWER COMPANY

(Registrant)

/s/ Kevin P. Larson

Vice President and Principal
Financial Officer

